|    | Listed on State Register   | SURVEY NUMBER:   |
|----|--|--|
| 77 | VT ACHP (1980)   |  |
|    | Date:  | 0409-62  |
|    | Date.  | NEGATIVE FILE NUMBER:  |
|    |  | 77-A-59  |
| 97 |  | UTM REFERENCES:  |
|    | STATE OF VERMONT   |  |
|    | Division for Historic Preservation   | Zone/Easting/Northing  |
|    | Montpelier, VT 05602   |  |
|    | Montpeller, vi 05002   | 7.0 ((0(00 hogorho   |
|    |  | 18 662630 4930540  |
|    | HISTORIC SITES & STRUCTURES SURVEY   | U.S.G.S. QUAD. MAP:  |
|    | Individual Structure Survey Form   | Underhill, Vt.   |
|    | Individual structure survey rorm   |  |
|    | ii ii  | PRESENT FORMAL NAME:   |
|    |  | A  |
|    | LOOTINGY. Chittondon   | ORIGINAL FORMAL NAME:  |
|    | COUNTY: Chittenden   |  |
|    | TOWN: Jericho  | Joseph Brown-Hiram Day   |
|    | LOCATION: corner Brown Trace Rd. &   | PRESENT USE: dwelling  |
|    | D+ 17  | ORIGINAL USE: dwelling   |
|    | Rt. 15   |  |
|    |  | ARCHITECT/ENGINEER:  |
|    | COMMON NAME: Harley Irish residence  |  |
|    | Harley Irish residence   | BUILDER/CONTRACTOR:  |
|    | - house  | HPOTHDBIN/CONTINUOTOR.   |
|    | FUNCTIONAL TYPE: house   |  |
|    | OWNER: Harley Irish, Brown Trace   | PHYSICAL CONDITION OF STRUCTURE:   |
|    | approx. Dd Toxiche V4  | Excellent Good   |
|    | ADDRESS: Rd., Jericho, Vt.   | Brita D Good   |
|    |  | Fair Poor  |
|    | ACCESSIBILITY TO PUBLIC:   | THEME:   |
|    | ACCESSIBILITI TO TOURIS.   | STYLE: Gothic Revival  |
|    | Yes 🔲 No 🔳 Restricted 🔲  |  |
|    | LEVEL OF SIGNIFICANCE:   | DATE BUILT:  |
|    | Local State National   | (a. 100)   |
|    | LOCAL SCACE MACLOMAL   |  |
|    | GENERAL DESCRIPTION:   |  |
|    | Structural System  |  |
|    | I Foundation: Stone Brich  | k ☐ Concrete ☐ Concrete Block ☐ ☐  |
|    | 1. Foundation: Stone Bile.   | Concrete D concrete man  |
|    | 2. Wall Structure  |  |
|    | a. Wood Frame: Post & Bea  | am ■ Balloon □   |
|    | L. Total Desmine Maganess  | Brick   Stone   Concrete   |
|    | b. Load Bearing Masonry:   | DETCK [] Stolle [] colletere []  |
|    | Concrete Block   | -  |
|    | c. Iron 🛮 d. Steel 🗖   | e. Other:  |
|    | C. IION L. G. Decer L.   | ■ Porrd : Patton □ Wood Shingle□   |
|    | 3. Wall Covering: Clapboard  | ■ Board & Batten □ Wood Shingle □  |
|    | Shiplap   Novelty  | Stucco   Sheet Metal   Aluminum  |
|    | Agnhalt Shingle [] Bric  | k Veneer   |
|    | Asphart Shingle L  | A veneer   |
|    | Bonding Pattern:   | Other:   |
|    | 4. Roof Structure  |  |
|    | a. Truss: Wood Iron  | □ Steel □ Congrete □   |
|    |  |  |
|    | b. Other:  |  |
|    | 5. Roof Covering: Slate  | Wood Shingle ☐ Asphalt Shingle ☐   |
|    | Of the Market III Dull to the  | □ Polled □ Tile □ Other.   |
|    |  | ☐ Rolled ☐ Tile ☐ Other:   |
|    | 6. Engineering Structure:  |  |
|    | 7. Other:  |  |
|    | /. Other.  | Cunolac Dormers Chimneys   |
|    | Appendages: Porches Towers   | Cupolas Dormers Chimneys   |
|    | Shede T Ells T Wings Ot  | her: d   |
|    | To C Chales Cable Win D Che  | d □ Flat □ Mansard □ Gambrel □   |
|    | ROOI Style: Gable   nip   She  | the Company of the Co |
|    | Jerkinhead  Saw Tooth  Wit   | h Monitor     with Belicast  |
|    | With Parapet   With False From   | t Π Other:   |
|    | With rarabee   with rates  | 1  |
|    | Number of Stories: $\frac{1}{5}$ $\frac{1/2}{2}$ Number of Bays: $\frac{5}{2}$ | central  |
|    | Number of Bays: 5 x 2  | Entrance Location:   |
|    | Number of Sujet  |  |
|    | Approximate Dimensions: 32 x 22  |  |
| 37 |  |  |
|    | THREAT TO STRUCTURE:   | LOCAL ATTITUDES:   |
|    | TAREAT TO STRUCTURE!   |  |
|    | No Threat   Zoning   Roads   | <b>-</b> 11  |
| 5  | Development Deterioration  | Mixed Other:   |
|    |  | II .   |
|    | alteration D Othors  | II.  |
|    | Alteration  Other:   | ll .   |
|    | Alteration  Other:   | the state of the s |
|    | Alteration   Other:  |  |

## ADDITIONAL APCHITECTURAL OR STRUCTURAL DESCRIPT ON

Window heads are flared and rounded. The centrally located gabled wall dormer is adorned with an arrowhead motif. The door incorporates round arched lights. The entrance porch has chamfered posts and stick style balustrades. 2 dormer windows light the upstairs of the rear wing. The rear porch has turned posts. Vertical plank walls.


## RELATED STRUCTURES: (Describe)

- Shiplap sided barn with gable roofed cupola.
- 2. Shed with exposed rafter tails.
  - Garage with asphalt siding.
  - Small shiplap sided barn.

## STATEMENT OF SIGNIFICANCE:

A blending of styles, this house combines the steep gables characteristic of the Gothic Revival style with the Italianate style round arch utilized in its window heads and door lights. In addition, behind the clapboards are wood planks. Framing with wood planks is typical of earlier houses and probably the early house was modernized as new architectural styles became fashionable.

## REFERENCES:



|             |             | - |
|-------------|-------------|---|
| SURROUNDING | ENVIRONMENT | : |
|             |             |   |

Scattered Buildings [ Moderately Built Up Densely Built Up Residential Commercial Agricultural Industrial Roadside Strip Development

Adele Cramer

Div for Historic Preservation

DATE RECORDED: 5/20/77



Vt. Div. for Historic Preservation Chittenden County Jericho 5/77 Harley Irish Residence, 0409.62 NE 77-A-59 Adele Cramer